


PRINCE








MODLOFT



ASSEMBLY INSTRUCTION


PRINCE MD322-CK





ASSEMBLY INSTRUCTION PRINCE MD322-CK


PARTS




① x 2 (Left - Right)




② x 1




③ x 1



④ x 1



HARDWARE



① x 4



② x 4



③ x 4



1/4 x 1"

④ x 48



1/4 x 1 1/2"

⑤ x 4




1/4"

⑥ x 4




1/4"

⑦ x 4



⑧ x 2

TOOL



⑨ x 1




⑩ x 1



ASSEMBLY INSTRUCTION

PRINCE MD322-CK








ASSEMBLY INSTRUCTION

PRINCE MD322-CK

STEP 3




STEP 4






ASSEMBLY INSTRUCTION PRINCE MD322-CK






ASSEMBLY INSTRUCTION PRINCE MD322-CK

STEP 7



PRINCE








MODLOFT



ASSEMBLY INSTRUCTION

PRINCE MD322-K






ASSEMBLY INSTRUCTION

PRINCE MD322-K


PARTS




① x 2 (Left - Right)




② x 1




③ x 1



④ x 1



HARDWARE



① x 4



② x 4



③ x 4



1/4 x 1"

④ x 48



1/4 x 1 1/2"

⑤ x 4




1/4"

⑥ x 4




1/4"

⑦ x 4



⑧ x 2

TOOL



⑨ x 1




⑩ x 1



ASSEMBLY INSTRUCTION

PRINCE MD322-K








ASSEMBLY INSTRUCTION

PRINCE MD322-K

STEP 3




STEP 4






ASSEMBLY INSTRUCTION PRINCE MD322-K






ASSEMBLY INSTRUCTION PRINCE MD322-K

STEP 7



PRINCE








MODLOFT



ASSEMBLY INSTRUCTION

PRINCE MD322-F






ASSEMBLY INSTRUCTION

PRINCE MD322-F


PARTS




① x 2 (Left - Right)




② x 1



③ x 1



④ x 1



HARDWARE



Ⓐ x 4



Ⓑ x 2



Ⓒ x 2



1/4 x 1"

Ⓓ x 40



1/4 x 1 1/2"

Ⓔ x 2




1/4"

Ⓕ x 2




1/4"

Ⓖ x 2



Ⓗ x 1

TOOL



Ⓘ x 1




Ⓙ x 1



ASSEMBLY INSTRUCTION

PRINCE MD322-F








ASSEMBLY INSTRUCTION

PRINCE MD322-F

STEP 3




STEP 4







ASSEMBLY INSTRUCTION PRINCE MD322-F

STEP 5




STEP 6






ASSEMBLY INSTRUCTION PRINCE MD322-F

STEP 7



PRINCE








MODLOFT



ASSEMBLY INSTRUCTION

PRINCE MD322-Q






ASSEMBLY INSTRUCTION

PRINCE MD322-Q


PARTS




① x 2 (Left - Right)




② x 1




③ x 1



④ x 1



HARDWARE



① x 4



② x 2



③ x 2



1/4 x 1"

④ x 40



1/4 x 1 1/2"

⑤ x 2




1/4"

⑥ x 2




1/4"

⑦ x 2



⑧ x 1

TOOL



⑨ x 1




⑩ x 1



ASSEMBLY INSTRUCTION

PRINCE MD322-Q








ASSEMBLY INSTRUCTION

PRINCE MD322-Q

STEP 3




STEP 4






ASSEMBLY INSTRUCTION PRINCE MD322-Q






ASSEMBLY INSTRUCTION PRINCE MD322-Q

STEP 7



PRINCE








MODLOFT



ASSEMBLY INSTRUCTION


PRINCE MD322-T





ASSEMBLY INSTRUCTION PRINCE MD322-T


PARTS




① x 2 (Left - Right)




② x 1




③ x 1



④ x 1



HARDWARE



① x 4



② x 2



③ x 2



1/4 x 1"

④ x 32



1/4 x 1 1/2"

⑤ x 2




1/4"

⑥ x 2




1/4"

⑦ x 2



⑧ x 1

TOOL



⑨ x 1




⑩ x 1



ASSEMBLY INSTRUCTION

PRINCE MD322-T








ASSEMBLY INSTRUCTION

PRINCE MD322-T

STEP 3




STEP 4





ASSEMBLY INSTRUCTION PRINCE MD322-T





ASSEMBLY INSTRUCTION PRINCE MD322-T

STEP 7

