


MD510 Assembly Instructions

Parts




① X1




② X1


③ X4 M8*25-1/4"




④ X4 $\phi 8*30$




⑤ X4 $\phi 22*\phi 10*2$




⑥ X1 5mm



1:



2:



3:

